

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number ST01693LA

This Certificate issued to

Global AirWorks
19933 Harrison Ave.
City of Industry, California 91789

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*

**Certification basis is set forth in Type Certificate Data Sheet*

Original Product Type Certificate Number: A35EU

Make: Airbus

Model: A310, Model 304

Description of Type Design Change: Installation of AirWorks Cockpit Door Surveillance Systems in accordance with FAA Approved AirWorks Index List Document No. IL23008, Revision NC, dated July 7, 2004, or later FAA approved revision. AirWorks Airplane Flight Manual Supplement Document No. AFMS232010012, Revision Original, FAA approved on November 4, 2004, or later FAA approved revision, is required as part of this modification.

Limitations and Conditions: This installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, Suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.


Date of application: September 16, 2002

Date of issuance: November 12, 2004

Date reissued: October 24, 2006, March 16, 2010

Date amended:

By direction of the Administrator


(Signature)

Manager, Systems & Equipment Branch,
Los Angeles Aircraft Certification Office

(Title)



Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.